






Pointe tournante type P



Pointe tournante **standard 60°**



Tournage



Rectification



Taillage



Contrôle

Ref.	Déclinaison	ØA	ØB	C	D	E	L	Rot. Max. Tr/mn	Charge axial Max.daN	Charge radial Max.daN	Concentricité ≤ mm
GE1068	SV70	20	10	15	13	43	71	7000	400	60	0.002
GE1006	SV102	22	12	17	13	57	87	7000	600	80	0.002
GE1001	N°1	22	12	17	13	57	87	6500	600	80	0.002
GE1007	N°2	29	18	22	19	58	109	6000	800	150	0.002
GE1012	N°3	40	24	30	24	85	139	5000	1100	350	0.002
GE1016	N°4	49	31	38	28	108	174	4000	1400	500	0.002
GE1020	N°5	60	40	50	33	136	219	3000	1800	700	0.002